# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,820,543 B2

Page 1 of 1

DATED

: November 23, 2004

INVENTOR(S): Hironobu Takasawa et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# Column 5,

Line 52, change "includes a damper and a damper shaft." to -- includes a clamper and a clamper shaft. --

#### Column 6,

Line 18, change "kozo, mitsumata," to -- kozo, mitsumata, --.

Line 33, change "damper rotatable about the damper shaft" to -- clamper rotatable around the clamper shaft --.

### Column 7,

Line 33, change "damper" to -- clamper --.

# Column 9,

Lines 31, 50 and 53, change "damper" to -- clamper --.

### Column 10,

Lines 16 and 17, change "damper" to -- clamper --.

#### Column 12,

Lines 10, 32, 35, 37 and 45, change "damper" to -- clamper --.

Lines 19, 20 and 49, change "dampers" to -- clampers --.

Signed and Sealed this

Fifth Day of July, 2005

JON W. DUDAS
Director of the United States Patent and Trademark Office